

# TGB TECHNICAL BULLETIN

NO. CCP960411

**Topic:**  
**R50X stator (CDI)**

**Scope:**  
R50X model only.

**Current condition and problems:**

We received claims that our R50X scooter would suddenly turn off and then could not start anymore due to stator problem.

**Countermeasure:**

1. Change stator supplier
2. To execute full inspection
3. Modify the CDI and replace.

**Put into mass production frame number:**

After frame no. 642755 is a modified one

**as example :**



**Picture 1 :**  
**original CDI (P/N: GE5139902)**



**Picture 2**  
**new CDI (P/N: 441019)**

**Edited by TGB sales dep. Stephen Su**