



TGB ALARM SYSTEM REMOVAL

We have found that in some cases it may be required to remove the Alarm system from scooter. Units that are affected are the 2006 R5, 2006 R9 and 2006 R50X.

The decision to remove the alarm may be made for the following reasons.

1. The customer or dealer does not wish to have the alarm system on the unit.
2. The alarm system has become defective or is found to have an excessive current draw on the battery.

The following steps will help in the removal of the alarm system.

1. Remove the front headlight panel.
2. Locate and Identify alarm system.
3. Disconnect the nine pin connector and remove the alarm box, horn and ground wire.
4. Disconnect the 2 white and blue pin connectors from the black and yellow wire coming from the ignition switch.
5. Reconnect the 2 black and yellow pin connectors as shown in picture.



