

**Topic:**

R50X stator defect

**Scope:**


R50X model

**Current condition and problems:**

We received claims that while riding R50X, the engine would suddenly turn off and then could not start anymore due to stator problem.

**Temporal Countermeasure:**

1. Change stator supplier
2. To execute full inspection
3. Tape a blue tape at the end of stator cable to recognize as picture 2.

**as example :**

Picture 1 : original stator cable without blue tape    Picture 2 : new stator cable with blue tape

